

[REDACTED] **TOP SECRET** [REDACTED]

(c) **NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER**

Attachment to [REDACTED]

1 May 1966

Page 1
Copy 56

REFERENCE: [REDACTED] HEN ROOST ANTENNAS (RADAR SITE 2)
SARY-SHAGAN ANTIMISSILE TEST CENTER, USSR

1. SIGNIFICANCE: ANALYSIS OF THE FIRST LARGE SCALE KH-7 COVERAGE OF THE HEN ROOST FACILITIES CONFIRMS THAT BOTH THE NORTH AND SOUTH ANTENNAS HAVE BEEN DISMANTLED.
2. REMARKS: NO DEPLOYMENT OF THE HEN ROOST OR SIMILAR ANTENNAS HAS BEEN OBSERVED IN THE USSR.
3. LOCATION: 6 NM SW OF THE MAIN SUPPORT BASE AT THE SARY-SHAGAN ANTIMISSILE TEST CENTER (SSATC).

[REDACTED]

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.

GROUP 1
Excluded from automatic
downgrading and declassification

TOP SECRET [REDACTED]

[REDACTED] **TOP SECRET** [REDACTED]

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Attachment to [REDACTED]
1 May 1966

Page 2

25

25

25

5. FIRST IDENTIFICATION:

[REDACTED]

[REDACTED]

6. NEGATION DATE:

NONE

7. SUBSEQUENT COVERAGE:

33 KH-4 MISSIONS.

8. DIMENSIONS/
SPECIFICATIONS:

NONE

9. MISSION READOUT:

THIS MISSION RECONFIRMS THE FACT THAT THE REFLECTOR AND CLUTTER SCREENS AT HEN ROOST ANTENNA NORTH AND THE REFLECTOR SCREEN AT HEN ROOST ANTENNA SOUTH HAVE BEEN DISMANTLED. FOOTINGS REMAIN AT THE SITES OF THE FORMER SCREENS OF BOTH HEN ROOST ANTENNAS.

CRATES CAN BE SEEN AT BOTH SITES AND IN THE SUPPORT AREA. THOSE AT HEN ROOST ANTENNA NORTH MEASURE APPROXIMATELY 30 X 10 FT.

SUPPORT FACILITIES AT HEN ROOST ANTENNA NORTH SHOW NO APPARENT CHANGE. SUPPORT FACILITIES AT HEN ROOST ANTENNA SOUTH INCLUDE 5 SMALL SUPPORT BUILDINGS, A WATER STANDPIPE, A T-SHAPED CONTROL BUILDING, AND 2 PROBABLE COOLING PONDS. ROOF DISCOLORATION IS VISIBLE ON THE CONTROL BUILDING, AND COULD INDICATE ANTICIPATED DISMANTLING OR REPAIR. THE

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.

TOP SECRET [REDACTED]

[REDACTED] **TOP SECRET** [REDACTED]

25

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Attachment to [REDACTED]
1 May 1966

25

Page 3

SUPPORT AREA FOR THE HEN ROOST ANTENNAS IS COMPOSED OF 23 BUILDINGS AND
A TRANSFORMER SUBSTATION, AND SHOWS NO APPARENT CHANGE.

[REDACTED]
25

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.

TOP SECRET [REDACTED]

25

TOP SECRET





Approved For Release 2007/01/18 : CIA-RDP78T05939A001600070005-2

HEN ROOST ANTENNAS (RADAR SITE 2)
SARY-SHAGAN ANTIMISSILE TEST CENTER, USSR
45-56N 73-38E

HEN ROOST ANTENNA SOUTH

HEN ROOST ANTENNA NORTH



TOP SECRET

25X1
25X1

25X1
25X1